

Fee Schedule Clarification for Private Drinking Water Wells
7-10-08

125.00 fee for a site visit in response to the application for a repair due to an unknown malfunction that would be remedied by the driller through some maintenance function. Maintenance to a well is defined as pump repair or replacement or disinfection.

375.00 fee for a “repair” to an existing well for the adjacent property search and the initial site visit to establish the well site and existing conditions. Where “repair” means work involved in deepening, reaming, sealing, installing or changing casing depth, perforating, screening, and cleaning, acidizing, hydrofracturing or redevelopment of a well excavation, or any other work that results in breaking or opening the well seal.

A construction authorization will be issued as a “repair” with a drawn site plan. After the repair work is performed the second site visit for the wellhead completion authorization. After that date we would be responsible for a third site visit to collect a water sample within 30 days.

375.00 fee for all new well construction following the procedure above with the addition of the grout inspection. The applicant will apply for a repair without the specific knowledge of work needed to remedy the well problem. We will need to make the initial site visit and speak with the driller to understand whether a construction authorization is needed.